

5bbl number 1 scratch on the top surface



5bbl number1 shape change on the top



5bbl number 2 scratch on the left side





Shape change at the top    serious scratch on the top surface





5bbl number 3 scratch on the top and side and serious shape changed on the top



5bbl number 3



Scratch on the bottom

5bbl number5 shape changed on the top few more scratch on the surface







5bbl number6

Scratch on the surface and cip pipe change shaped also the connect part broken



5bbl number6



5bbl number6 too many scratches on the surface

